

Location & number of catch basin markers inspected during 2018 reporting period:

<u>Location</u>	<u>Markers Inspected</u>	<u>Number Replaced</u>
Jennings Mill	89	18
Jennings Mill Road	22	0
Keeneland	21	1
Silverleaf	46	4
Belfair	49	2
Total:	<u>227</u>	<u>25</u>

